



000005

SUBJECT: MLF DELAY/CONNECTION ISSUE

SOLUTION: USE RAISED RING CONCEPT:



Raised inner lead tip Raised GND ring

3/2/01

WITNESS:

3/2/01